## Brookstown Rd - Evangeline St Area Rehabilitation Project (Phase 1)

City-Parish #10-AR-BD-0039

Advertisement for Bid: 4<sup>t</sup> Project End: 4<sup>t</sup>

## 4<sup>th</sup> Quarter 2010 4<sup>th</sup> Quarter 2012

Rehabilitation of the sewer collection system is a comprehensive physical process that begins with cleaning and inspection of sewer pipes and manholes. Typical rehabilitation repairs include pipe and manhole replacement and trenchless technologies that minimize above ground disturbances, such as curedin-place pipe liners.




One of the first steps in rehabilitation includes a physical inspection of manholes and pipes to identify blockages.



Simply cleaning the pipes and manholes in preparation for the physical inspection removes blockages, debris and roots.





## Brookstown Rd - Evangeline St Area Rehabilitation Project (Phase 1) Facts

For this project:

- Approximately 271,678 linear feet of pipeline were inspected and rehabilitated
- Approximately 1,113 manholes were rehabilitated or replaced

Estimated Construction Cost: \$10.6 M

## <u>Design Consultant:</u> Program Rehab Mgmt Team

Construction Contractor: Grady Crawford